

AUTOMOBILE TRANSPORTER LLC DBA EXPEDITE LTL SERVICES

2646 Dupont Drive Suite 60-134
 IRVINE, California 92612
 MC Number: 60498
 Phone: 8777079297
 Email: info@automobiletransporter.net

BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: OR-10450-Q4K1R7				
ORIGIN Wheel Kinetics 1909 W. Gardner Ln Tucson, AZ 85705 Contact: Ryan Phone: (401) 545-0885		DESTINATION Michael Koekuk Court San Diego, CA 92117 Contact: Phone: (858) 531-7579		
VIN 3C63RRGL3EG304540	Year / Make / Model 2014 RAM 3500	Type Pickup (4 doors)	Color White	Odometer 76691
Inspection notes: One key.				
<div style="display: flex;"> <div style="flex: 1;"> <ul style="list-style-type: none"> BR-Broken CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed </div> <div style="flex: 2; text-align: center;"> </div> </div> <p style="text-align: center;"> CR Circles — pickup damages; CR Rounded rectangles — delivery damages; </p> <p style="text-align: center; background-color: yellow; padding: 5px;"> See inspection photos and details: https://bol.mysuperdispatch.com/z6QXL </p>				
Notes: One key.		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / May 23, 2019 / Dennis 		Vehicle received in good condition except as noted above. Destination Signature		
Driver Signature / May 23, 2019 / Tony Duong 		Driver Signature / Tony Duong		

Carrier will not be liable for:

1. Damage caused by leaking fluids, battery acids, cooling system antifreeze solution or individual fallout.
2. Radio antennas that extend more than three (3) inches above fender or hood level of the vehicle being transported.
3. Loss or damage to any or all personal items left inside the vehicle.
4. Mechanical functions, exhaust assembly, alignment, suspension, or tuning of the vehicle being transported when the damage is not due to carrier/driver negligence.
5. Auto rental accruals.
6. Delivery of any particular schedule. Contact of carriage to governed by terms and conditions of the Uniformed Straight Bill of Lading.

Carrier liability limited to current "blue book" value for make, model, year of manufacturing, and odometer mileage.

Automobiles are designed for road use and may acquire small scratches, scuff, dents, or abrasions. This inspection represents the general overall condition, but is not inclusive.

The carrier/driver will take all precautions to safely deliver the vehicle/equipment.